

PAINTCOR

SUPREME QUALITY *Since 1986*

TRI-3 SILVER ALUMINIUM

Description and application

CATEGORY

Waterproofing / UV Protection

DESCRIPTION

TRI-3 is a water based Silver Aluminium, based on a modified pure acrylic. TRI-3 has been specially formulated to completely seal and protect new fabric on fabric covered Aircraft from the elements. TRI-3 has an elongation of over 200 percent allowing it to stretch with your aircraft fabric with no cracking. It is recommended that top coats applied, must also be flexible.

FEATURES

- Waterproof
- Very flexible
- Excellent U.V. protection
- Adhesion promoted
- Light barrier

SURFACE PREPARATION AND APPLICATION FOR NEW FABRIC

1. Clean all applied new fabric with methylated spirits and water mixed in a 1:1 ratio. Allow to dry.

Surface Preparation

1. TRI-3 is supplied ready for use.
2. Apply 1 coat with a sponge brush to all hard surfaces and tapes. Allow 2 hours @ 25°C to dry.
3. Apply 1 coat to all fabric with a sponge brush, ensuring to force the Silver Aluminium into the cloth. Make sure no ridges or excessively thick areas are left. Allow to dry.
4. Using a 400 grit water paper, lightly sand any imperfections from the surface (Caution: do not sand through the Silver Aluminium coating to the fabric). Remove all sanding dust.

Paintcor cc
Reg No: CK 86/19456/23
VAT No: 4830119311

Members: G. Williams, G. Adendorff
W. Williams

Head office: 1494 Mailship
street, Laser Park, Honeydew, 2040
Postal Address: P.O. Box 917,
Northriding, 2162

Email
sale@paintcor.co.za

Website
www.paintcor.co.za

Tel: 011 794 2885
Fax no: 011 794 6955



SABS
ISO 9001:2008



PAINTCOR

SUPREME QUALITY *Since 1986*

5. Apply a second coat to all fabric by spray application. (Spray: 2.5mm spray nozzle with no dilution). Should dilution be necessary, then dilute with distilled water at no more than 5% of total product. Allow 2 hours to dry between coats @ 25°C.
6. Apply by spray as many coats as necessary to completely cover and seal the fabric (no light must be visible through the fabric once final coats have been applied).
7. Allow at least 48 hours @ 25°C to cure before over coating with top coats.
8. Top coats: Please contact Skyworx Aviation for recommended top coats.
skyworxaviation@icon.co.za

Application Method

Sponge Brush, Brush, Spray, Roller

Cleaning equipment

Clean all equipment immediately after use with water.

Conditions to avoid

1. Do not paint below 8°C.
2. Do not paint if humidity is 80% or more.

Paintcor cc
Reg No: CK 86/19456/23
VAT No: 4830119311

Members: G. Williams, G. Adendorff
W. Williams

Head office: 1494 Mailship
street, Laser Park, Honeydew, 2040
Postal Address: P.O. Box 917,
Northriding, 2162

Email
sale@paintcor.co.za

Website
www.paintcor.co.za

Tel: 011 794 2885
Fax no: 011 794 6955



SABS
ISO 9001:2008



